

Answers to Questions

And

Statement on Break-in

135 W. Fremont Street, Stockton

On October 26, 2015, DGS was notified that a break-in had occurred at the property. Subsequent investigation revealed damage to several electrical panels including service to the building's HVAC system. Repairs have been completed in order to restore lighting and security to the building. However, repairs to the entire electrical system will not be completed prior to the sale of the building.

- The elevator is operational.
- FY 2013-14 Audited Financial Statement could be supplied as Financial Information.