

The 2007 triennial edition of the California Code of Regulations, Title 24 (California Building Standards Code) applies to all occupancies that applied for a building permit on or after January 1, 2008, and remains in effect until the effective date of the next triennial edition. The following errata items will be officially published and distributed by ICC and IAPMO. (Note: Items shown underlined denote the errata item that was revised)

Errata items for the 2007 Triennial Edition of Title 24, Parts 2, 4, and 5 of the 2007 California Code of Regulations (CCR)

(Updated on 1-23-09)

- **Part 2 - California Building Code, Vol. 1 & 2**

- **Chapter 2 – DEFINITIONS** – Replace the definitions for ‘HOTEL or MOTEL’ and ‘MOTEL’ that were inadvertently removed during codification of the 2007 cycle information. Only the acronym for the Division of the State Architect (DSA/AC) should have been removed. The Housing and Community Development agency has maintained these definitions for their use and they have requested the definitions be reinserted back into chapter 2 of the 2007 CBC.
- **Chapter 4, Section 443.4.7.5 Ventilation rates.** – Correct last sentence as shown;

443.4.7.5 Ventilation rates. *Mechanical exhaust ventilation systems shall provide a minimum ventilation rate not less than 1 cubic ~~foot~~ foot per minute per square foot [0.00508 m³/(s·m²)] of floor area, or six air changes per hour, ~~wh continuously at the designed ventilation rate. whichever is greater. Systems shall operate~~ whichever is greater. Systems shall operate continuously at the designed ventilation rate.*

- **Chapter 10** – Matrix Table Correction – Add an ‘X’ to the matrix adoption table for the HCD agency under Section number 1003.1.
- **Chapter 11A** – Correct internal reference to Chapter 11A Figure 11A-6C.

Section 1107A DEFINITIONS Immediately following the heading and before the first definition in this section there should be a sentence that reads;

For the purpose of this chapter, certain terms are defined as follows:

The last three headings for the 1107A definitions sections are shown incorrectly. The following is the correct order of these three items.

1107A.24-X (No definitions)

1107A.2425-Y (No definitions)

1107A.26-Z (No definitions)

Section 1114A.4.7 Other intermediate landings. *Other intermediate landings shall have a dimension in the direction of ramp run of not less than 60 inches (1524 mm). (See Figure ~~11-A6C~~ 11A-6C).*

- **Chapter 11B** – Clarification for duplicated code sections for Section 1115B and 1117B, detectable warnings. Section 1115B.4.7 has been moved to Section 1117B.9

1117B.9 ~~4415B.4.7~~ Accessible kitchen sinks. Sinks required to be accessible shall comply with this subsection.

1. A clear floor space at least 30 inches by 48 inches (762mm by 1219mm) complying with section....
...underneath the sink (see Figure 11B-1D).

2. Each accessible sink shall be a maximum of...
... against contacts. There shall be no sharp or abrasive surfaces under sinks.

3. Faucet controls and operating mechanisms shall be operable with one...
... of accessible designs.

2. Noncommercial kitchen and counter bar sinks. A clear floor space of at least 30 inches by 48 inches (762mm by 1219 mm) complying with Section 1118B.4 shall be provided in front of a sink to allow forward

~~approach. The clear floor space shall be on an accessible route and shall extend a minimum of 19 inches (485 mm) underneath the sink (see Figure 11B-1D).~~

~~Each accessible sink shall be a maximum of 6 ½ inches (165 mm) deep. Sinks shall be mounted with the center of the rim no higher than 34 inches (865 mm) above the finish floor. Knee clearance that is set at least 27 inches (685 mm) high, 30 inches (762 mm) wide, and 19 inches (485 mm) deep shall be provided underneath sinks. Hot water and drain pipes exposed under sinks shall be insulated or otherwise configured so as to protect against contact. There shall be no sharp or abrasive surfaces under sinks.~~

~~Kitchen and counter bar sinks located in common use areas shall have faucet controls and operating mechanisms operable with one hand in accordance with this chapter and shall not require grasping, pinching or twisting of the wrist. The force required to activate controls shall be no greater than 5 lbf (22.2 N). Lever operated, push type and electronically controlled mechanisms are examples of acceptable designs.~~

- **Chapter 17A** – Correct metric conversion for the exception of Section 1704A.6.2.1 Structural glue-laminated timber.

1704A.6.2.1 Structural glue-laminated timber. Manufacture of all structural glue-laminated...

Exception: Special inspection in not required for noncustom members of 5 1/8 inch ~~(30mm)~~ (130mm) maximum width and 18 inch...

(Remaining portion of section to remain unchanged)

- **INDEX** – Correct Section number shown on page 667 for STAIRWAY CONSTRUCTION; Projections.....Change Section number from ~~1009.11.7~~ to 1012.7
- **Part 4 – California Mechanical Code**
 - **Chapter 4, Section 418.5 Alarm Systems.** (Change the word “an” to “and” in the first sentence of the paragraph and change the word “cubit” to “cubic” at the end of the paragraph as follows)

~~An Audible ~~an~~ and visual alarm system shall be installed to alert sterilizer operating personnel if the air flow falls below design ~~cubit~~ cubic feet per minute(L/S).~~

- **Part 5 – California Plumbing Code**
 - **Table 4-1 Instructional Language** (Modification to clarify the use of a reference Table A)

Table 4-1

Minimum Plumbing Facilities¹

Each building shall be provided with sanitary facilities, including provisions for persons with disabilities as prescribed by the Department Having Jurisdiction¹⁹.
~~For requirements for persons with disabilities, Chapter 11A or 11B of the California Building Code shall be used. The total occupant load shall be determined by the minimum existing requirements.~~ The minimum number of fixtures shall be calculated by fifty (50) percent male and fifty (50) percent female based on the total occupant load. The occupant load and use of building...

“Remaining language and exceptions for Table 4-1 are to remain as printed in the 2007 edition of the CPC”.