



etc. Additional visual instructions on a console with a touch screen would only clutter the console with unnecessary verbiage.

Also, our proposal for 11B-411.2.1.2.4 revisions specifies that the required information will always be displayed and just as intuitive as other car call stations.



