

CLIENT: State of California, DGS/BPM  
 Attn: Vince Paul  
 1304 O Street Suite 300  
 Sacramento, CA 95814

PROJECT: BATESON

SAMPLE COLLECTED BY: Vince Paul

TYPE OF SAMPLE: Tape (x2)

ANALYSIS DATE: 4/10/02

TYPE OF ANALYSIS: Direct Preparation, Microscopic Examination

REPORT DATE: 4/10/02

REPORTED & REVIEWED BY: Network Environmental Systems (NES)

**BULK SURFACE SAMPLE RESULTS  
 BATESON BUILDING, 1600 9<sup>TH</sup> STREET  
 SACRAMENTO, CALIFORNIA  
 APRIL 10, 2002**

**DIRECT MICROSCOPIC EXAMINATION**

The "Tape Lift Samples" collected demonstrated the following:

Sample Set and Location	Results/Identification
<b>41002-Bateson -02 Federal Program Suite 320, stained carpet adjacent to concrete block.</b>	<b>Mostly soot, skin flakes, fibrous materials; no obvious sign of fungal growth observed.</b>
<b>41002-Bateson -04 Early Start, Suite 330, stained carpet in N.E. Corner.</b>	<b>Mostly soot, skin flakes, fibrous materials; no obvious sign of fungal growth observed</b>

**Note: Massive > Numerous > A Few > A Trace > No Growth**